DATE Ø120Z 28 DEC 1962	CLASSIFIED MESSAGE	2	STING  4  5  6
TO DIRECTOR	EO 12958 3.3(b)(1)>2		90
ACTIONE OSA (1-2-3-4-5-6-7-8-9-1)  INFO :S/C (11)  TOR: Ø134Z 28 DEC 1962		P	IN 60542
PRITY OXCART	0	CITE	7425

NO NIGHT ACTION

INS DIFFICULTIES. I DO NOT HAVE EXACT DETAILS BUT APPARENTLY WE CAN EXPECT TROUBLES WHEN OUTSIDE TEMPERATURES ARE LOW. WAS 3 DEGREES F HERE THIS MORNING. FOR MANY REASONS THIS AIRCRAFT IS NOT, AT LEAST AT THE MOMENT, CAPABLE OF BEING LAUNCHED WHEN OUTSIDE TEMPERATURES ARE LOW. THIS COULD BE A MOST DIFFICULT PROBLEM IF MESSAGES I SEE REGARDING EIELSON STAGING ARE SERIOUS.

FUEL AND OIL COULD NOT STAND OUTSIDE TEMPERATURES FOR TWO PLUS HOURS WHILE INS PLATFORM BEING ERECTED. IF THIS IS PRACTICABLE BELOW ZERO. I INTEND TO DISCUSS THIS GENERAL AREA WITH NORM

END OF MESSAGE

APPROVED FOR RELEASE
DATE: AUG 2007

CACOUP 1

Cacoup 1